

Network Video Recorder

Version: V3.2.7 build161013

Release Note

(2016-11-7)

Firmware Basic Information	Firmware Version:	V3.2.7 build161013
	SDK Version:	V5.2.5.15_build20160906
	ONVIF Protocol:	ONVIF 2.4
	IVMS-4200:	V2.5.3.102 build20160914
	Web Component:	V4.0.1 build 150708

Reason of Upgrade

Add new function and fix bugs for better performances on DS-96xxxNI-F (/H) NVR.

Firmware Upgrade

New Features

1. [USB flash disk debugging]

Support printing NVR kernel running information to USB flash disk in txt format for debugging.

2. [Video Wall]

Support adjusting image contrast, brightness, chroma and saturation of video wall output.

3. [System logs]

Support recording flash writing times in system logs for debugging.

Optimization

1. [Live view]

Fix the issue that live view might fast forward when user switch screens.

2. [RTSP]

Fix the issue that client can't get audio from NVR with RTSP protocol after channel 32.

3. [System]

Optimize NVR's stability in situations below:

- (1) User changes IP camera's stream type frequently;
- (2) User exports IP camera list in camera management interface;
- (3) HDD is damaged and detected by NVR;
- (4) User clicks alarm icon in left bottom corner of live view interface frequently;
- (5) NVR receives massive face detection messages.

4. [Live view]

Fix the issue that IP camera's image stays in live view interface even if IP camera is disconnected.

Supported Product List		
DS-96128NI-F16	DS-96128NI-F16/H	DS-96256NI-F16
DS-96256NI-F16/H	DS-96128NI-F24	DS-96128NI-F24/H
DS-96256NI-F24	DS-96256NI-F24/H	

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd.
No. 555 Qianmo Road, Binjiang District, Hangzhou 310052, China
Tel: +86-571-8807-5998
FAX: +86-571-8993-5635
Email: support@hikvision.com